


*Exhibit 6, Attachment C*


*Wave Graphics from Marine  
Management & Consulting*

## Scrub Island Marina, BVI

Area exposed to north and south, minimal protection by land to east



Summer Trades, no swells entering harbor, Image Date: August 29, 2012



Winter Trades, minimal swells entering harbor, image date: November 29, 2005



# North Sound Marinas, Virgin Gorda, BVI

Area exposed to northwest and north, but well protected by land to east and south



Summer Trades, no swells entering harbor, Image Date: March 25, 2013




Winter Trades, No swells entering harbor, image date: November 29, 2005




## East End St Thomas, USVI Marinas

Area exposed to north and east, although in shadow of Tortolla.



Summer Trades, some swells entering harbor, Image Date: August 10, 2017




Winter Trades, No swells entering harbor, image date: February 5, 2017


# TYPICAL NORTHERLY WINTER WIND




CORAL HARBOR, ST JOHN



EAST END ST THOMAS




SCRUB ISLAND, BVI




NORTH SOUND, VIRGIN GORDA, BVI




# TYPICAL EASTERLY SUMMER WIND




CORAL HARBOR, ST JOHN



EAST END ST THOMAS



SCRUB ISLAND, BVI



NORTH SOUND, VIRGIN GORDA, BVI